

# PONY 2/4

## Field Update v.06142019

### Remove Pod Chute Reinforcement Bar

**UNIC**

ESPRESSO ENGINEERS

12407 Mukilteo Speedway Suite 250-B

Lynnwood, WA 98087

+1 (866) 295-8642


usa-service@unic-sa.com

To correct problem associated with Chute Reinforcement Bar sometimes interfering with the pods dropping into the drawer.




Remove the Reinforcing Bar from both Chutes.

Can be done in place, no need to remove the Chutes first.



Pull the rubber posts out




Push the bar off with a screwdriver




Remove bar and discard



Press the posts back in place



Pull from the rear to seat



Trim the rubber tab off